

- 2 -

16

in a field owned by Pulsifer Bros. Ltd., 400 ft from the hangar.

This accident appears to me to be a case of too fast a cockpit check, and the gasoline cock not being fully in the ON position.

Trusting this will be satisfactory,

I remain, .

Yours truly,

(sgd) Donald C. Keith,  
Instructor.