

graphs of a second failure of the Chambly Dam, but this time of a portion of it where there were no sluice gates to weaken or lighten the structure, as in the portion previously washed away.

The conclusion is therefore inevitable that the dam was not of sufficient weight, nor was its base so grooved into the underlying bedrock, to prevent it from being pushed bodily forward.