34

DEPARTMENT OF TRANSPORT AIR SERVICES BRANCH CIVIL AVIATION DIVISION File No: - 5008-E4-2

JAN 2 A.M.

5008-E4-2

File

File

Rm. 44, Trans-Atlantic Administration Building, Montreal Airport, Dorval, P.Q.

SUBJECT: - Accident Report
Aircraft Registrations: CF-EDB

Director of Air Services, Department of Transport, No 3 Temporary Building, Ottawa, Ont.

ATTENTION: - Superintendent Air Regulations.

- 1. The following report of accident involving the above noted aircraft is submitted for your information and record, please.
- 1. Date of Accident: December 22nd, 1951
- 2. Place: Baie St.Paul, Quebec. 3. Type of aircraft: Stinson 108
- 3. Type of aircraft: Stinson 108
  4. Pilot's Name: G. Lafrenière Licence: C-5711
- 5. Number of people injured, (if any) nil 6. Extent of injuries, (if applicable) nil
- 7. Extent of damage to aircraft: Right wing: bent spars. Five broken ribs. Right strut bent. Left wing tip damaged.
- 8. Type of flying, (Private, Commercial, etc.) Commercial.
- 9. Summary of events immediately prior to and including the accident: Pilot took off from field and when 10 feet off the ground made right turn to avoid obstruction shead. While turning right, wing tip touched a fence. Aircraft lost flying speed and fell on the ground, scraping left wing tip.
- 10. Opinion as to the cause of the accident: Pilot at attempting turn with insufficient airspeed.
- 11. Remarks: Letter of warning will be sent to pilot.

COPY GH 5802-29171

for District Controller, Air Services

/jg