

4 FT. SIDEWALK

PORTION OF BROKEN DOWN
BRICK WALL

Position of vehicle
AFTER ACCIDENT

Exhibit A

AK

Broken Steel Fence

SLIDE MARKS CAUSED BY ROBBING

CANYAL
COTTON
STEEL on
SIDEWALK

Sketch of

ROAD ACCIDENT 14 Nov. 45

W.D. Vehicle No. CM 4202845

TIRE MARKS come to
END 2 1/2 ft from CURB

Pressure marks
14 in. from
CURB

TIRE MARKS
3 FT from
CURB

WHEEL TRACKS
17 FT 5 IN. from CURB
15 FT 5 IN. from CURB

30 MPH SPEED LIMIT SIGN

81 ft. around CURVE

Direction of
Travel

To Epsem

Not true to scale

RA Hayfield 21