

Shelburne.

Fog-whistle machinery generally overhauled and repaired.

Seal Island.

A new set of tubes fitted to boiler, seams caulked, new coal shed built and general repairs effected.

Brier Island.

Hard patch inside furnace and two soft patches placed on outside shell of boiler. New steps built at entrance to whistle house.

Cape d'Or.

The sum of \$200 has been expended in repairing road from Horse Shoe Cove to Station.

The following is a statement of the repairs and improvements effected at the different light stations during the past year :—

Egg Island.

A new clockwork machine to revolve the illuminating apparatus has been fitted up and the old one brought off for necessary repairs. The landing slip has been renewed and sundry small repairs done to buildings.

Pope's Harbour.

A new boathouse has been erected, planks of lantern deck renewed and deck covered with canvas.

Sheet Rock.

A crib work block built at end of landing slip and slip repaired. A new boat supplied.

Peggy's Point.

An iron lantern, formerly in use at Ironbound Island, has been fitted up in place of the old lantern, which was found to be worn and unfit for service, and a new deck and base built to receive lantern.

Westhaver Island.

On the 28th June last a fire occurred at this station resulting in the total destruction of the lighthouse and contents. The oil store and boathouse were saved. An investigation into the cause of the fire has been held by the Inspector, but no satisfactory conclusion has been arrived at. The fire is supposed to have been the work of an incendiary.

A temporary pole has been erected until a permanent light can be established.