

Q

Quantity dynamo	87
" " data	page 81
" " firing	107
" " method of using	88
" " testing	122
Quantity of electricity, unit of ..	140
Quarrying	64
" Gibraltar method	65
Quick match ..	72

R

Racks, in magazines	page 67
Rails, cutting with guncotton or dynamite	55
Recipes, sundry	page 82
Resistance coils	164
" " box of	165
" " Firing	167
" " Post Office pattern	166
" connecting unknown resistance to measuring apparatus ..	196
" electrical, definition of	128
" of a conductor, measurement of, by fusion of fine wire ..	214
" " " " " " Latimer Clark's differential gal-	
vanometer	203
" " " " " " tangent galvanometer	207
" " " " " " Wheatstone's bridge method ..	197-202
" " " " " " with 3-coil galvanometer ..	208-210
" " galvanometer, measurement of	204
" of copper and iron wire	page 79
" " fine wire at the point of fusion, measurement of ..	215
" liquid, measurement of, by deflection of a galvanometer ..	218
" " " " " " fusion of fine wire	221
" " " " " " Kempe's method	223
" " " " " " Latimer Clark's differential galvanometer ..	222
" " " " " " Mance's Wheatstone's bridge method ..	217
" very high, measuring	205
" " low, rough test of	211
" unit of	142
Reversing key	157
Rock, blasting	63

S

Selection of arrangement of circuit	98
Service cables	93
" " resistance of	page 79
Simple circuit	97
Sine galvanometer	172
Shunts, for galvanometers	176-178
Solder for circuit wires	page 83
Soldering	100
" fluxes for	page 83
Sources of electricity for use with high tension fuzes	89
" " " " " " wire fuzes	79
Standard cells, Latimer Clark's	161
" " Modified Daniell's cell	160
Stockades, cutting an opening in, by means of explosives ..	58
Stone piers, demolishing with explosives ..	66
Storage of guncotton	15, 28, 29
" " gunpowder	27

T

Tamping, effect of	4
" amount required in various cases	pages 72-79