

This micrograph shows a metal surface with a dark, irregular corrosion product. The product is elongated and has a rough, crystalline texture. It is situated on a lighter, more uniform metal surface. The background metal surface shows some fine, granular texture.