7. Number of persons (a) killed Nil

(b) seriously injured two minor

- 8. Nature of accident Stall
- 9. Type of flying (Private, non-scheduled, ferry, etc.) Private
- 10. Opinion as to the cause of the accident (Use ICAO Manual of Accident Investigation) Pilot error and inexperience.
- 11. Damage Write-off
- 12. Infractions of: (a) The Air Regulations Nil
  - (b) Air Navigation Orders Nil
- 13. Disciplinary action proposed taken Nil
- See pilot's statement which is self explanatory. Following a complete stall out of a turn, the aircraft, at a very steep angle struck water. At this location the depth of water was about 12 to 13 feet. The severe damage sustained by the aircraft was caused by contact with the bottom of the lake. It was fortunate in that a motor boat was near to render assistance to the aircraft's occupants.

WIND PHYINE THINK ACCIDENT LOCATION

Note: (1) This report is in amplification of Director accident notification required.

Inspection Instructions Paragraph 1.2.2 refers.

(2) To be submitted in duplicate.

Messis