

- equipment should operate in an ambient temperature of between - 30° C to + 70° C.
- a suitable complement of spare parts, spare units and test equipment should be provided.
- a test centre, complete with training aids should be provided.
- engineering services in respect of the setting to work of the equipment and the training of maintenance and operating personnel should be provided.
- all equipment should be suitable for mounting in small transportable shelters.
- equipment should be transistorized to the maximum extent practicable.
- equipment should be new.