

structure either of the suspension, cantilever or arch type. At the Split Rock site it would be necessary to do considerable grading to the approach and build a roadway for some distance, but it would get rid of a sharp curve and it would not

This image shows a blank, aged, cream-colored page, likely an endpaper or flyleaf of a book. The paper has a slightly textured appearance with some minor discoloration and small dark spots, possibly due to age or handling. A vertical crease is visible near the right edge, suggesting it was once part of a bound volume. The page is otherwise empty of any text or markings.