


a high rate of speed and too close together and standing close to track when trains are passing, are some of the many acts of carelessness on the part of employees which result in accidents and injury, and to which special attention should be given.

Appr.



ORDER
BOLTS
BY
THESE
NUMBER

#1

#2

#2A

#3A

#3B

#3C

#4

#4A

#4B

#4C