Index

A

PAGE

Acadia Coal Co., mine-rescue station of 23
Alberta, mine-rescue station of 24
Apparatus—See under *Mine-Rescue Apparatus* and *Rescue Apparatus*.
Atmospheric air, volumes of nitrogen in 3
volumes of oxygen in 3
Austria, classification of mines in 11
mine-rescue laws in 11

B

Belgium, mine-rescue laws in 10
Breathing devices, comparison of 6
British Columbia, mine-rescue law of 26
mine-rescue stations in 27, 28

C

Canada, cause of high death rate in coal mines of 1
Carbonic acid, volumes of, in atmosphere 3
volumes of, in exhaled air 4
Carbon dioxide, percentage added to exhaled air 4
provision made for absorption of 4
Classification of mine-rescue apparatus 3
Coal mining, cause of high death rate in Canada 1
cause of low death rate in Europe 1
cause of loss of life in United States 1
Compulsory mine-rescue equipment 1
Courrières disaster 7

D

Delaunaye, M., apparatus completed by 2
Dominion Coal Co., rescue station of 21

E

Europe, establishment of mine-rescue stations in 1
European legislation for safe-guarding lives of workmen 1
Exhaled air, percentage of carbon dioxide in 4
volumes of oxygen in 4
volumes of nitrogen in 3

F

France, mine-rescue laws of 9

G

PAGE

Galibert respirator 2
Garforth, W. E., rescue stations, equipment, etc 37
rules for recovering coal mines after explosions and fires 37
Germany, control of mines in 12
mine-rescue laws of 12
Goupillière, Haton de la, on failure of early rescue apparatus 3
Government mine-rescue stations in British Columbia 27, 28
Great Britain, mine-rescue laws of 13
Growth of mine-rescue work 2

H

Hall and Snelling, article on waste of life in American coal mining 1
Helmets versus mouth-breathing devices 6
History and growth of mine-rescue work 2

L

Laws requiring mine-rescue apparatus in mines of:
Austria 11
Belgium 10
British Columbia 26
France 9
Germany 12
Great Britain 13
Russia 8
Legislation for safe-guarding lives of workmen in Europe 1

M

Mines, in Austria, classification of 11
in Germany, control of 12
Mine-rescue apparatus, automatic supply 4
compressed air supply 5
compressed oxygen supply 4
liquid air supply 5
oxygen supply generated from sodium-potassium peroxide 5
Mine-rescue apparatus, classification of 3
compulsory equipment of 1
present types of 3
report on by Committee of South Midland Coal Owners 7
requirements of 40
with piping and pumps or bellows 6
Mine-rescue car, Nova Scotia Steel and Coal Co., description of 23