	Part.	Page
S		
SUBSIDIES. *See* "Railway Subsidies"	III	3
SUPERINTENDENT of P. E. I. Ry., Report of the	I	95
SUTTON, Mr. J. *See* "Mechanical Accountant"	I	79
STE. ANNE'S LOCK :—		
Description of works	I	11
Expenditure	II	16
Operation and maintenance	I	47
Superintending Engineer, Report of the	I	131
Water on mitre sills	I	136
ST. LAWRENCE District :—		
Superintending Engineer, Report of the, on construction	I	151
" " " maintenance	I	157
Water on mitre sills	I	160
ST. LAWRENCE River and Lakes :—		
Description of routes	I	5
Expenditure on surveys	II	9
North Channel, straightening	I	155
ST. OURS Lock and Dam :—		
Description of lock	I	13
Expenditure	II	20
Operation and maintenance	I	46
Superintending Engineer, Report of the	I	133
Water on mitre sill	I	136
ST. PETER'S Canal :—		
Description of works	I	16
Expenditure on construction	II	5
Operation and maintenance	I	49
Lockmaster and Collector, Report of the	I	168
T		
TAY Canal, expenditure. *See* also "Rideau"	II	14
THOMPSON, Mr. W. G. *See* "Welland"	I	162
TOLLS on Canals, Consolidated Tariff of	V	154
TRANSCONTINENTAL railway communication	I	3
TRENT Canal :—		
Description of works	I	24
Expenditure	II	23
Operation and maintenance	I	47
Superintending Engineer, Report of the	I	139
Water level at each lock	I	144
W		
WELLAND CANAL :—		
Damages to property	I	165
Description of canal and branches	I	9
Expenditure	II	15
Fines collected	I	166
Operation and maintenance	I	49
Sketch showing section of lock	I	30
Superintending Engineer, Report of the	I	162
Water on mitre sills	I	167
WILLIAMSBURG CANALS :—		
Description of works	I	8
Expenditure	II	13
Operation and maintenance	I	49
Superintending Engineer, Report of the	I	152, 158
Water on mitre sills	I	160
WILLIAMS, Mr. T. *See* "Chief Accountant and Treasurer"	I	59, 92
WINDSOR BRANCH :—		
Accountant and Treasurer, Statements of the	I	92
Chief Engineer, Report of the	I	91
Description of the road	I	4
Earnings	I	26
General Manager, Report of the	I	90
Length of route	I	18