

Bridge Abutment Resting on Piles
Demolished owing to Sliding of Blue Clay Soil
During Trainfilling

PLATE I.