§

High-tension fuzes 42
" " defects that may occur in 118
" " measuring resistance of 210
" " sources of electricity for use with 89
" " testing 118
Hose, Ord's 74
" powder 73
Horsley's blasting powder 18
Houses, blowing down 62

I

Igniting an explosive 3
India-rubber bags for guncotton primers.. .... 49, page 72
" " gunpowder .... 52, page 72
Instantaneous Bickford's fuze.... 75
" " " placing in a gallery.. 52
Instantaneous current, effect of, on a galvanometer 179, 180
Instantaneous leader.... .... 73, 74, 75
" " connecting to Bickford's fuze.. .... 74, 75
" " rate of burning .... page 79
Insulating head of electrical fuzes 102
" joints in electrical cables 100
Insulation fault in a cable, to detect position of.... 213
" resistance of cables, rough measurement of 210, 212
Insulator, definition of.. 130
Iridio-platinum bridge of wire fuzes 37
Iron wire, resistance of.. .... page 79

J

Jointing Bickford's instantaneous fuze.... 75
" circuit wires 99–101
" iron wires 100
" and testing box, for Field Service 109
Joint, Britannia 100
" three-way 101
" two-way 100

K

Key, contact 156
" firing 105
" " reversing 157

L

Land mines, preparation of charge for 52
Latimer Clark's differential galvanometer 183
" " standard cell.... 161
Leaders, precautions when using .... page 62
" slow and instantaneous 70–75
Leads, gauge of, for electrical measurements 153
Leclanche firing cell 83
" " " making up 84
" " " cement for .. .. page 82
" " " data .... page 81
" test cell 163
Lightning conductors .. .. page 68

M

Magazines, dimensions of roof.... .... page 67
" " " walls .. .. page 67
" earthen traverses between store magazines .... page 69
" floors of .... page 68