In the fusion power system, since energy has to be invested to maintain the reaction, there is no possibility of a runaway reaction as any change from the normal operation would tend to halt the process.

A very long term possibility is the use of advanced fuel cycles where the energy is created entirely in the form of charged particles with no resultant radioactivity, and with the potential of direct conversion to electricity with efficiencies of the order of 90 percent.