










CUTTING OF METALS.

Swivel Tool-holders.

(See page 266.)



Scale 1 to 3.