

Piper Cub J3, Serial #2150, Registration CP-EE0 was received at  
on Aircraft Ltd. for repair and renewal of the Certificate of Airworthiness.  
The following work was carried out:

Fuselage

Right front landing gear fitting repaired.  
Fuselage diagonal brace tube right side at Station #2 was straightened.  
Right side fuselage cowl support channel repaired.  
Fuselage Cowling repaired.  
New fabric placed over repaired area and doped.

Starboard Wing

Trailing edge repaired.  
Trailing edge of ribs #4 and #5 repaired.

Port Wing

Trailing edge of rib #4 repaired.

Right Float

Copper stripping repaired at step.

Left Float

Inboard chine strip repaired.

Float Undercarriage

Left rear diagonal members repaired.  
Right front diagonal member repaired.  
Wings and Fuselage were given two coats of pigmented dope.  
Aircraft assembled using new bolts where necessary.  
Fire Extinguisher renewed.  
Tension Spring added to fuel shut-off cock.  
Aircraft re-rigged.  
All controls checked for security.  
Aircraft weighed and empty weight and Centre of Gravity computed.