

for the purpose of drawing the water out of the boiler and pipes.

Paint all screens as may be directed, in three coats, and prick out the design with gilding—gold-leaf to be used. All wall coils to be bronzed to approval. The boilers and all pipes to be black varnished, two coats. Painting.

It is to be distinctly understood that everything necessary for a complete and perfect job in boilers, piping, or other portion of the work, must be furnished, though not specially mentioned in this Specification.

In no case will bearing timbers be allowed to be cut without the consent of the person in charge of the works, and in case of such cutting, iron fitches or ties must be provided and placed to make good original strength. All cutting and making good to be done under the supervision and to the satisfaction of the person in charge.

All chases will be lathed over with wire lathing, so that the plastering can be carried through.