

PLACE	DATE	TIME	SUMMARY OF EVENTS	REFERENCE TO APPENDICES
Camp Borden, Ont.	4-6-42		Yale 3378 ground-looped on main aerodrome, Camp Borden, at 1530 hours. R.128742 LAC Levy, M.D. pilot uninjured. Due to inexperience pilot failed to apply corrective measure after bouncing, allowing Port Wing to strike runway. Categorized C.2	
	5-6-42		Nil.	
	6-6-42		Yale 3370 bounced on landing on main aerodrome, Camp Borden, 0835 hours. Pilot Officer D. Denbigh (J.9677) and R.122805 LAC Tressam, E.J. pilots uninjured. Left tire blew out causing Oleo Leg to collapse. No damage.	
			Yale 3377 ground-looped on main aerodrome, Camp Borden, 1655 hours. Pilot R.60069 LAC Ham uninjured. Pilot over-corrected swing to right while landing causing ground-loop. No damage.	
	7-6-42		Nil	
	8-6-42		Yale 3367 ground-looped on main aerodrome Camp Borden at 1040 hours. Pilot R.135003 LAC Taylor, E.D. uninjured. Port Wing dropped when pilot levelled off too high and stalled in 45 degree. No damage.	
			Harvard 3817 forced landing at Dundalk, Ont. Flying Officer J.D. Armstrong (J.5707) pilot slightly injured. Took off slightly up hill on soft ground, failed to rise sufficiently struck two fences and two cows. Under-carriage, both wings, centre section and propeller were damaged. Categorized B or A.	
			Harvard 3004 made landing at night at R.1 Edenvale, Ontario, 2245 hours. R.115227 LAC Downs, J. pilot, uninjured. Failed to lower undercarriage on landing, damaging wings, propeller, ailerons and flaps. Disciplinary action being taken for negligence. Categorized C.2.	
	9-6-42		Dr. Stephen Leacock, Stephen Leacock, Jr. and Professor John Culliton of McGill University were visitors in the Officers' Mess.	
	10-6-42		A funeral party from No. 1 S.F.T.S. attended the funeral of LAC Gibson at Meaford. LAC Gibson was killed in an aircraft accident at St. Eugene, Ont. F/L Butcher, Protestant Chaplain at No. 1 S.F.T.S. conducted the Service.	

52