District File No. 5008-B18-16 (ARM)

AIRCRAFT ACCIDENT REPORT

General To: Director of Air Services Department of Transport Ottawa, Ontario Controller, Civil
Attention: Superintendent, Air Regulations

Moneton _District

1. (a) Date September 29, 1957

15:15 ADT (b) Time (standard):

2. (a) Type of Aircraft Piper J3

Use 24-hour clock (b) Nationality and

CF-BRP

(c) C. of A. Valid to August 27, 1958

Registration Marks (d) C. of R. Valid

Yes (X) No ()

3. Name of Owner, Operator or Hirer Halifix Flying Club

4. (a) Crew information

Name	Duty	Age	Licences & Ratings			Experience		
			Туре	No	Expiry date	Total	On type	
							Total	Within 90 days
Joseph Donald Bellefontain	t a very ater	is de	ne siver	QMP- 3155	2/9/58	Illeba	ofic see evalence da eigne tudda ee 50:00 hrs	6:00 hrs
	render of m	390 08		CONTRACTOR CONTRACTOR	se in the		Tt tes fi	

(b)	Now	enrolled	in	Annuand	School	Yes	()	
				Approved		No	6)	

Approved School graduate

(c) Name and location of school Halifax Flying Club

(d) Instructor's name G. I. Steeves

Category 11

(e) Instructor's name who recommended

issue of pilot's licence G. I. Steeves Category 11

(f) Instructor's name who conducted flight test

G. I. Steeves

Category 11

5. (a) Last point of departure

Waverley Lake Waverley Lake

(b) Intended destination

44

6. (a) Place of accident Latitude

47' N. **63** ° 35' W. Longitude

Altitude ASL _

(b) Terrain: Mountain () Prairie () Arctic () Maritime () Bush () Inter-city -populated or semi-populated areas-₹)

(c) Weather:

Ceiling

Visibility

Wind Speed and direction NW/15

Light Rain Snow

Medium

Were icing conditions encountered? Yes ()

No (T)

Dew point

N/A Temperature

Turbulence: light (x) medium () heavy ()

(d) Did pilot obtain weather forecast or attend a meteorological briefing? Yes () No (x)

Hail

Fog

(Over)