

In installing the plant I would advise that 10 stamps be placed in operation first, but the power plant and rock breaker should be large enough for the 20-stamp mill. By installing the 10-stamp first, the ore broken by development can be milled and the producing stage reached at an earlier date.

The water power should be developed at once, and a ten-drill compressor be installed. This will be sufficient capacity to provide for all requirements for some time.

FRED M. WELLS.

Vancouver, B. C., November 4th, 1910.



ENTRANCE TO LOWER TUNNEL