

59. No person shall have in his possession, for use in the mine, beyond the place at which lamps are examined by an official of the mine, any unlocked safety lamp so defective or insecure that reasonable observation by him could have detected such defect or insecurity.

60. No miner or other workman shall be permitted to introduce into the mine any stranger, or person employed by them, on any pretence, without the consent of the owner or manager.

61. Miners and all other persons who shall have occasion to pass through any trap-door, shall thereupon closely shut the same, and shall on no account leave it open. On discontinuing work at the end of a shift, and especially where no work is to be done in the mine the following day, care must be taken by every workman closely to shut all trap doors, so as to prevent the proper current of air necessary for ventilation from being diverted.

+ 62. All workmen are prohibited from entering or remaining in any place throughout the whole mine, where not absolutely required by duty to be at the time.

63. Miners and all other persons except drivers and rope riders are expressly forbidden to ride on empty or full cars in or about any part of the mine.

64. Miners and all other persons are prohibited from defacing or removing marks which may be made on any part of the workings, for the guidance of the workmen in their operations. All workmen are forbidden to displace, injure or damage in any way, the props, cars, rails, or any part of the machinery, gearing and apparatus.

65. Meetings of miners and other workmen in a body within the workings, or in any of the roads, or air courses or at the mine-mouth are strictly prohibited.

66. No workman shall be permitted to enter, or to continue in the mine while in a state of intoxication.

67. No person shall try the workings or the goaves for fire-damp with a naked light; and no person shall smoke tobacco, or take into any mine which is worked with safety lamps, tobacco pipes or tobacco for the purpose of smoking, or matches or any apparatus for striking a light other than that approved for lighting shots. All persons may be searched for tobacco, pipes and matches, but the person making such search shall be first examined by two of the workmen of the mine.

68. No person in a place of trust shall depute another person to do his work, without the sanction of his superior officer, and no person in a place of trust shall absent himself without having previously obtained the permission of his superior officer for his term of absence.

69. It shall be the duty of anyone receiving personal injury in or about the mine to immediately report such injury to the manager, overman or fireman.

To

1. enter
2. and ing p
3. with vented of mi
4. late a provis order of inv