

EXTRA PARTS OF HUMMINGBIRD MOWER.

No.	\$ c.	No.	\$ c.
1A. Double Washer for Connecting Rod.....	0 10	712. Spiral Spring for do.	0 05
2. Driver's Seat.....	1 25	713. Inside Shoe.....	2 00
50A. Driving Wheel.....	0 00	714. Outside Shoe, with Spring	2 25
57A. Right-hand Ratchet.....	1 25	714. Spring for Outside Shoe..	0 75
58A. Left " ".....	1 25	715. Scythe Button.....	0 10
61. Composition Boxes.....	1 00	716. Guard Finger.....	0 50
69. Finger Bolt.....	0 10	716A. End " ".....	0 50
75. Track Clearer Slide.....	0 25	716. Plate for Guard Finger...	0 10
Thumb Nut and Bolt for Slide.....	0 15	719. Leading Wheel.....	1 00
Thumb Nut for Slide.....	0 05	719. Roll and Bolt for Leading Wheel.....	0 50
86. Spring Key.....	0 05	720. Folding Iron on Pole.....	0 30
93. Right-hand Spring Pawl.....	0 50	722. Lever Ratchet and Axle..	1 00
94. Left " " " ".....	0 50	723. Lever Socket.....	1 00
95. Linch Pin.....	0 05	730. Long Brace.....	1 50
96A. Axle Washer.....	0 05	731. Short " ".....	2 00
151A. Lever Pawl.....	0 25	732. Connecting Rod.....	2 00
153A. " Handle.....	1 25	734. Lifting Chain.....	0 75
153. " Latch.....	0 25	735. Crank Fender.....	0 50
159. Pin for Crank Balance.....	1 25	736. Main Seat Spring.....	1 50
480. Track Clearer Iron with Slide.....	1 25	737. Dash " ".....	0 50
700. Frame.....	10 00	738. Wrought Hinge Joint.....	4 00
701. Lid of Tool Box.....	1 00	739. Grass Guard.....	1 00
702. Foot Plate.....	0 50	743. Finger Bar, drilled.....	6 00
703. Shield for Bevel Wheel..	1 00	" " with Guards.....	15 00
704. Bevel Wheel.....	3 50	" " " ".....	20 00
705. Internal Gear and Bevel Pinion.....	4 00	744. Complete Scythe.....	5 00
706. Spur Pinion.....	0 75	745. Knife Section.....	0 25
707. Shipper Casting.....	0 50	746. Blank " ".....	0 25
708. " Slide.....	0 25	748. Axle with Gear and Ratchet.....	10 00
709. " Handle.....	0 75	" " without Gear and Ratchets.....	3 50
710. Axle Clamp.....	0 50	750. Crank Shaft, with Balance	4 25
711. Crank Balance with Pin..	2 00	" " without ".....	2 00
712. Button for Tool Box... ..	0 10		

TO FOLD THE BAR FOR MAKING OF TRANSPORTATION