

- (i) GL Mk IIIC An interim report on operational trials of this appt has been completed and distributed.
- (11) Magslip Transmission System A test was made at Research Enterprises Ltd. Toronto, on possible errors introduced into a Magslip Transmission System when using the CDX generator as a source of supply. This generator has a poor wave form but tests indicate that the Harmonic content of the generator cutput is not sufficient to cause additional errors in the Magslip System.

CHEMICAL WARFARE AND SMCKE

- 26. (a) Inspection Board of UK and Canada (Week ending 26 Jun)
 - (1) Service Respirators Components Accepted

	Containers	0	a	•			•		a-	5	0	13	0	0	0	0			4	0			0	0	0		0	a	0	0	6		8	2	914 700 700	
	Facepieces	0	3	0	0		0			.01		0	0	a	0	0	0	0								0		4		0	4		8	1.	700	
×.	Assemblies	0		0		0	0	13	à	3	0	0	0	0	•	0	0	0	0	0	0	a	5	U		5	2	3	0	0	0		0	1	700	
	Haversacks		0	0	0	12	¢,	0	6		ø	ġ	5	0	2	۵	0	0	0	ų	ø	ö	0	0	0	0		Q	0	0	0				340	

(Over)

W.L.M. King Papers, Memoranda and Notes, 1940-1950, MG 26 J 4, Volume 259, pages C175059-C176576

PUBLIC ARCHIVES ARCHIVES PUBLIQUES CANADA