



DEPARTMENT OF TRANSPORT

INTRA-DEPARTMENTAL CORRESPONDENCE

910 Confederation Building,  
Montreal 2, Que., Sept. 15, 1947.

20  
2  
6-46

YOUR FILE  
5008-E6-25

SUBJECT  
D.H. 82 TIGER MOTH CF-EFY

OUR FILE  
5008-E6-25

Controller of Civil Aviation,  
Department of Transport,  
OTTAWA, Ontario.

A19625

1. Please find attached the following documents regarding the crash landing of the subject aircraft:

- (a) Copy of our letter to owner of aircraft.
- (b) Copy of Pilot Sullivan's Report.
- (c) Copy of a letter from owner of aircraft.
- (d) Copy of a letter from Senior Airport Controller, Dorval.
- (e) Copy of a letter to Airport Manager, Dorval.
- (f) Copy of Accident Report.

TRANSPORT-RECORDS  
 SEP 17 AM  
 File 5008-E6-25

2. This aircraft was inspected by the writer on the day following the accident, and it was noticed that the machine was fitted dual controls. Our records show that the two pilots of the aircraft at the time of the accident had licences endorsed for D.H.82. Structural damages were observed on fuselage, tail unit, both upper main planes, and undercarriage. The propeller was also broken.

3. Submitted for your information and records, please.

*J. F. Gournier*  
J. F. Gournier,  
For District Inspector, Air Regulations.

JPF:gd  
Encl.

*already noted  
see file A 11331  
no la 11/33*

*D*