SIGNALS.

RYDGES, naging Director

RED signifies Danger, and means Stop.

GREEN signifies Caution, and means to Proceed slowly.

WIIITE signifies All Right, and means go on.

In addition to the above, and in the unavoidable abence of the ordinary Signals, anything waved violently p and down on the track, denotes Danger and the accessity to stop immediately.

Enginemen and Conductors in working Trains at Stations or Sidings DURING THE DAY, will observe the clowing Signals, which must be given QUIETLY:

The person giving the Signals must be stationed on the inginemen's or right hand side of Engine, unless the Train on a curve.

The Signal to START, will be given by stretching the rm and hand at right angles to the body; to STOP, by tetching Both arms and hands at right angles to the edy; to PROCEED CAUTIOUSLY, by waving slow, the right hand and arm down towards the track; to give BACK or FORWARD, by waving the arm or hand or from the body.

Trains must be worked during DARK, by the ordinary white, Green and Red Signal Lights; when a Round Redving Lamp is not in use, care must be taken to obscure be sides of the Square Signal Lamp.