

No attempt was made to ascertain the push of the propeller as McCurdy's Indicator requires re-adjustment, and re-testing before it can be used. This re-adjustment of the scale would take at least half a day to accomplish, so, as time is precious, it has been decided to put the engine and propeller on Cygnet II immediately without waiting to ascertain the push. A.G.B.

-----000-----