

PLACE	DATE	TIME	SUMMARY OF EVENTS	REFERENCE TO APPENDICES
Camp Borden, Ont.	16-4-42		Harvard 3185 ground looped on main aerodrome Camp Borden at 1155 hours. The Pilot, R127962 LAC Olding, J.M., was uninjured. Ground loop occurred while Pilot was engaged in circuits and landings when he failed to correct sufficiently for drift, allowing aircraft to swing to the left. Oleo leg, wing and aileron were damaged. Categorized C2.	
	17-4-42		Air Commodore G.F. Brookes, Air Officer Commanding, arrived by air from No. 1 Training Command to visit the station.	
	18-4-42		Assistant Section Officer (V30100) N.C. Hargan, RCAF (W.D.) (ADM) and <sup>79</sup> members of the RCAF (WD) reported for duty.  Flight Lieutenant L. de S. Duke of the Personnel Branch, arrived by air from A.F.H.Q. to visit the station.	
	19-4-42		Harvard 2636 ground looped on main aerodrome Camp Borden at 1500 hours. The Pilot, R113281 LAC Switzer, W.A. was uninjured. Accident which occurred during Instrument Flying Practice, was caused when aircraft was caught in a cross wind while landing and swung to left damaging starboard wing, oleo leg and aileron. Categorized C2.  Personnel of R.C.A.F. (W.D.) Participated in Church Parade. The Station Band was in attendance.	
			Harvard 2640 landed with wheels up on main aerodrome Camp Borden at 0125 hours. The Pilot, R110272, LAC Nagle, N.E., was uninjured. Accident occurred during night flying solo circuits when Pilot became excited because undercarriage failed to lower on first attempt. Categorized C3.	
	20-4-42		Harvard 2813 ground looped on main aerodrome Camp Borden at 1142 hours. Pilot Officer E.S. Henderson (Pending Gazettement) was uninjured. Ground loop occurred while Pilot was engaged in circuits and landings when he failed to correct for cross wind in time, causing aircraft to bounce and ground loop. Categorized C2.	

*RLG*