


PRICE LIST

Iron Working Machinery.



10 x 18 PEDESTAL SHAPER.

Shaping Machines.

10 x 18 Pedestal,
with Automatic Cross
and Circular Feeds,
\$375.00.

16 x 20 Gould &
Eberhart Pattern,
with Automatic Cross
and Down Feeds,
\$375.00.

Iron Planers.

WILL PLANE			UNIVERSAL FEED.	DOWN FEED OF MIDDLE HEAD.	WEIGHT. (About)	PRICE.
WIDTH.	HEIGHT.	LENGTH.				
18 in.	18 in.	4 $\frac{1}{2}$ in.	Hand	8 in.	2,250	\$400
24 "	24 "	6 $\frac{1}{2}$ "		10 "	4,200	525
24 "	24 "	7 "		10 "	4,500	555
26 "	24 "	8 "		10 "	5,000	650
30 "	30 "	10 "		12 "	10,000	990
36 "	30 "	10 "	Power	12 "	11,000	950
36 "	33 "	12 "		14 "	16,000	1,075
42 "	42 "	14 "		14 "	18,000	1,500
48 "	48 "	16 "		15 "	20,000	1,900