

LATIONS.

MANUAL OF ENGINEERS' CALCULATIONS.

29

80 parts of carbon requires 2527 cubic feet of oxygen.
5 hydrogen.

12635

473 cubic feet oxygen for hydrogen.
5 hydrogen.

2365

Then,

2365
12635

15000 cubic feet of air required for the
combustion of one hundred parts of coal.

