	Y YI					
					Damages to engines,	
			Killed.	Injured.		Cause.
No).	I	0	0	\$ 1,467.00	False clear manual block, operator unconsciously cleared signal. Not controlled.
No).	2	I	3	3,075.00	Failed to deliver meet order.
No).	3	2	13	4,500.00	Mistake in order. Time on order 12.50, should have been 12.15.
No).	5	I	I	5,000.00	Fouled end of double track, failed to read bulletin.
No).	6	2	23	6,400.00	Extra pass, ran by home and distant automatic signal, dense
						fog.
No).	8	0	7	9,220.00	C. and E. misread name of meeting station on meet order.
No		9		0	10,250.00	E. of light engine overlooked meeting order.
No	. 1	0	, I	20	11,852.00	C. and E. of N.B. pass. overlooked meeting order, also ran
						automatic.
No). I	I	0	4	14,914.00	Misunderstanding between conductors of east-bound and west-
						bound trains as to station for meeting the second part of
						separated train.
No	. I	2	5	2	18,600.00	Mistake in order, omitted the word "East" from name of
						station.
No	. I	3 .	I	13	21,000.00	Mistake in order, the order read, "Run from A to C, meet 7
						at B," it was delivered "Run from A to C, meet 7 at C."
Bulleti				, ,		D
			I	6	1,085.00	Passenger train ran 9,044 ft. past an automatic signal at stop.
No		3	I	9	3,350.00	Telegraph line out of order, trainmaster attempted to modify
N	1791			Ser of the ser	2 702 02	dispatcher's order. Engineer misread watch, making a mistake of one hour.
			0	2	2,500.00	Extra train was run without orders.
				0	4,000.00	E. forgot order, modified block system in service, signalman
No		0	0	32	6,380.00	gave train a clear signal, thinking that the train was to
						run to the far end of the siding, there to wait for the op-
						posing train.
No		-	0	25	12,874.00	C. and E. forgot one of three orders, met one train failed to
100		/		25	12,074.00	wait for another.
No		Q	I	31	13,184.00	Operator failed to deliver order to east-bound train. Had
110		0		3.	-3,104.00	three orders.
No		1	2	54	20,845.00	C. and E. of north-bound freight encroached on time of pas-
		9		37		senger, mistake in figuring the time from the time table.
No	. 10	2	10	21	25,000.00	Disregard of a despatchers order.
				alama dan	unilmanta min tenin	and the time out and out billed to one injured
Accidents, due to collisions, derailments, mis, train accidents, June 30th, 1908, 807 killed, 14,248 injured.						
				10	2 000 00	Confusion of orders, neglect to notice the sequence in the
No		2	4	40	3,000.00	numbers of the orders, and neglect of dispatcher to use
						the phrase "instead of."
No			3	27	6,000.00	Operator failed to deliver order.
		75.0	20	37	11,000.00	West-bound freight encroached on time of pass.
	1000		5	49	12,000.00	Mistake in writing order.
			4	2	13,300.00	Operator accepted order after the train had passed.
				59	22,297.00	Operator accepted order after train had passed.
Bulletin					2 200 00	Pass. standing at station run into by freight, at high speed
			4	14	2,200.00	Standing train not protected by flag.
			I	1	2,835.00	Operator accepted order after train had left.
			0	3	3,152.00	Operator having two orders, delivered only one.
			0	7	3,739.00 4,616.00	C. and E. of freight had order to run late one hour and thirty
NO.	10	,	7	11	4,010.00	minutes, forgot order and ran one hour and fifteen
						minutes late.
No			2	11	6,075.00	Misread dispatcher's order.
1			0	25	7,314.00	Failure to observe wait order.
			2	4		Failure to observe wait order, and failure of inferior train to
NO.	13)	2	4	0,000.00	clear five minutes.
No	T 4		2	5	8,300.00	C. accepted orders from operator, receipted for same, but
NO.	14	-	2	3	0,300.00	failed to take them with him.
No	IF			9	9,000.00	C. and E. having an order that second section of train would
110.	* 5			9	3,000,00	be one hour late, assumed that the first section was also
						late.
No	17	,	I	4	11,000.00	C. and E. misread name of station on order.
No. of the last of	,			William Barrell		