## DAILY DIARY

17-12-40	SUMMARY OF EVENTS
	Nil
18-12-40	Nil
19-12-40	Yales grounded for modification to aileron hinges.
20-12-40	Modification of Yales to aileron hinges completed and flying was resumed.
21-12-40	NII
22-12-40	Nil
23-12-40	Nil
24-12-40	Nil
25-12-40	Nil
26-12-40	NIL
87-12-40	Flying Accident
	Aircraft Yale 3385
	Time1040 hrs.PilotSgt. HoustonPupilIAC GodefroyDutyDual InstrumentInjuryNilPlace31 miles N.W. Cookstown, Ont.DamageC.5 crashAction takenNo. 1 Training Command advised.
	Yale No. 3382 was forced down at Georgetown, Ontario, due to foggy weather.
	Yale No. 3392 was forced down at Stayner, Ontario, due to foggy weather. Harvard No. 2707 was forced down at Lisle, Ontario, due to foggy weather.
	Harvard No. 2707 was forced down at Light Outer
-12-40	Harvard No. 2707 was forced down at Lisle, Ontario, due to foggy weather.
-12-40 -12-40	Harvard No. 2707 was forced down at Lisle, Ontario, due to foggy weather.
-12-40 -12-40 -12-40	Harvard No. 2707 was forced down at Lisle, Ontario, due to foggy weather. Nil
-12-40 -12-40 -12-40	Harvard No. 2707 was forced down at Lisle, Ontario, due to foggy weather. Nil Nil Nil
-12-40 -12-40 -12-40	Harvard No. 2707 was forced down at Lisle, Ontario, due to foggy weather. Nil Nil Nil
-12-40 -12-40 -12-40	Harvard No. 2707 was forced down at Lisle, Ontario, due to foggy weather. Nil Nil Nil
-12-40 -12-40 -12-40	Harvard No. 2707 was forced down at Lisle, Ontario, due to foggy weather. Nil Nil Nil

R.C