

1930 Budget.

PRINCIPAL'S RESIDENCE.

Mauve Room. Touch up window sills and floor at fire place.

Mr. Currie Jr's. Rooms. Tint ceilings and clean off paper in three rooms.

Top floor, North. Guest's bath room. Locate cause of wall stain.

Principal's bath room. Tint ceilings and wash down walls.

Swimming Pool. Paint ceiling, wash down walls and put heat deflector over two radiators.

Ball Room. Wash down and paint alcove. Wash down east and south walls.

Basement Hall. Wash down and paint.

Servant's Bath rooms. Wash down, tint, and paint five in number.

Kitchen Larder. Clean and Paint.

Butler's pantry. See to cause of leak from room above.

Butler's pantry larder. Wash down, tint or paint.

Lane fence. Relay foundations.

Roof drains, gutters, and roof of small rear gallery to be reconditioned, and where necessary, painted.


Gallery doors, exterior woodwork and windows to be reconditioned and painted.

McTavish St. gallery and front door and iron work to be painted and refinished.

In addition to this work there will be 8 to 10 rooms to be dusted down and floors to be refinished. This work is to be done when most convenient to Lady Currie, and when started is to be carried forward as rapidly as the number of men that can be engaged will permit.

As in all buildings this list is intended as a guide for the Workshops foreman and any have to be altered before this work is completed. He is, however reminded that all items are budgeted and no additional expenditures are to be incurred without consulting this office.

P.W.MacFarlane.
B.E.D.


Sub. Engineer.