PLACE	DATE	TIME	SUMMARY OF EVENTS
Camp Borden, Ont.	6=6=40		Oxford 1516, pilot Sgt. R. Reid, ran into Anson 3523 which was stationery, causing damage
			to both aircraft. Accident caused by failure of brakes and strong cross wind.
	and the second s	4	Major General Ashton, Inspector General, who was inspecting Army Area, visited Station and
			was driven around Hangar Area and Barrack Area by the Commanding Officer.
Camp Borden, Ont.	7-6-40		Nil -
Camp Borden, Ont.	8-6-40		Brigadier Stuart, Commandant R.M.C., Lt.Col. Burness, W/Cmdr. Higgins and 120 Gentlemen
Camp Borden, Ont.	0.630		Cadets visited Station and were taken on a tour of the training facilities.
	9-6-40		Church Parades.
Camp Borden, Ont.	10-6-40	, ,	Flying Officer Dyte reported on temporary duty. Phoned No. 1 Training Command we had rece
	- (1	,	Italy declared war and all Italians working for contractors were removed and special armed guards placed in hangars after dark.
Camp Borden, Ont.	11-6-40	9	Bishop Wells and Squadron Leader McNab visited Station.
Camp Borden, Ont.	12=6=40	9	Nil
Camp Borden, Ont.	13-6-40	1	Group Captain Mackworth arrived by air approximately 1200 hours, accompanied by W/C. Desmor
Camp Borden, Ont.	14-6-40		F.O. Miscampbell, San.Idr. Plante Wn Tonas
		7.	in Hudson. Sqn.Ldr. Plante and Mr. Jones remained overnight.  Sgt. Pilot Mews. passenger Set. Pilot Window Lander American
			Sgt. Pilot Mews, passenger Sgt. Pilot Winder landed Anson 3538 in Stony Lake. No injuries to personnel. Aircraft sank in 120 feet of water.
Camp Borden, Ont.	15-6-40		A bush fire occurred in the Army Area east of the Data
	3	10	A bush fire occurred in the Army Area, east of the Railroad tracks and north of the South Water Tower. An alarm was given but as the wind was blowing directly away from the R.C.A.F. area, the "all clear" was sounded. The fire was quickly extinguished by the Army.

REFERENCE TO APPENDICES

R.C.A.F. R. 65 15M-1-40 (3716) H.Q. 1062-3-50