10, 1907

y Council for power St. Catho: brick els, Trump Id, Ohio, 174 h.p., Jenckes ue., pair ,400.

SS.

s year in ched the ared with ast year. ssued to about 20 rear. ecords of of Vanionths of e of halt record of this year against a the corear. The greatly in bo8 being is against ue to the tal dwellnned. Fort Wilesents an ;, against months of

total inney strinmonth of nich is not history of louble last

rick manu-Alta., have St. Albert

liam Bryant tnership in s and have on hand. e Company, is working

o feet of 14 waterworks of New Listrict.

Buffalo Steel Fan for nanical draft is ourse of erecundertake to install these g full responsiults.

TOUR FAN s WITH US.

ADIAN FORGE CO. AITED IONTREAL

CANADIAN CONTRACT RECORD REPAIRING BROKEN SUB-

NEW COMPANIES.

George Ryan Shoe Company, Winnipeg, incorporated, capital \$50,000. Directors, George Ryan, Edmund L. Taylor and others.

July 10, 1907

Morris Brick Manufacturing Company, Morris, Man., incorporated, capital \$20,000. Directors, A. Chisholm, general merchant; John N. Phillips, hardware merchant and others.


Deloraine Milling Company, Deloraine, Man., incorporated, capital \$40,000. Directors, James Stead-man, W. S. Barker, George Patterson and others.

peg, Man., incorporated, capital \$100,000. Directors, W. F. Hull, barrister ; Louis Surpan, merchant, and others.

pany, Limited, Winnipeg, Man., incorporated, capital \$250,000. \$250,000. Directors, Edward Gurney, W. H. Carrick, W. F. Helliwell, and others, all of Toronto.

Company, Limited, Toronto, in-corporated, capital \$60,000. Incorporators, J. B. Bartram, C. M.

Limited, Toronto, incorporated, capital \$500,000 to carry on mining and smelting business. Incorpor-ators, W. C. Mackay, F. D. Byers and others.



350 feet long, and was laid on the rock bottom of the river in a normal water depth of 8 feet. After seven years of service without mishap an ice jam broke a single length of pipe at a joint. The current was

very strong and the ends of the ruptured pipe were 15 feet apart. Following, in reverse order, the method employed by Mr. Ward in laying the pipe in 1898, the pipe was disconnected at the shore ends, and then pulled ashore by means of horses, a capstan, block and tackle. The joints were melted out with kerosene heaters as they came ashore. The disconnected pipe was cleaned, treated with waterproof metallic paint, reconnected, and then hauled back to position. A test showed that it was tight.

