
ıll the v and their t conod of appli-

ats, to or and

withpoint

steam

e and



Section of the Squires Trap.

Omers and Engineers Endorse this Trap BECAUSE ...

No. 2 and 3 represent all there is to renew in case of wear. There are no other wearing parts and these, can be replaced at a minimum cost.

No. 4 represents the pivotally

attached Bucket.