	DATE	TIME	SUMMARY OF EVENTS
	11-4-43		When Harvard 2678 swung to right on landing at Main Aerodrome at approximately 1515 hours it groundlooped. R168258 LAC Schafer, G., the pilot, was not injured. Categorized C12.
		* **	At approximately 1000 hours Harvard 3340 groundlooped after landing on the Main Aerodrome R168258 LAD Schafer, G., pilot of the aircraft, was not injured. Categorized Cl2.
	12-4-43		0800 C.5000° V 10. Flying washed in 0800 hours, washed out 1120 hours. Solo. 3.20 hours
	- - - - - - - - -		At about 0525 hours Harvard 2556 spiralled in on take off one mile west of Camp Borden aerodrome. The pilot, GB1525005 LAC Smith, C.V. was killed. Categorized A.
	13-4-43	9.	0800 C.4 V.10 W/V220/5. Flying washed in 0800 hours - washed out 1930 hours. Sole all day. 111 hours. Night flying washed in 2030 hours - washed out 0220 hours. Total flying time 528.30. Night flying 46.50 hours.
	•		The propellor of Anson 7365 was damaged on the ice of Rice Lake when low flying, at approximately 10.30 hours. The pilot was R119871 Sgt. Woods, J.A. Other occupants were GB1559390 LAC McNamara, E. and R125448 LAC Dewar, K.B. No one was injured. Cat. Cl.
	14-4-43	7 - 4	0745 hours C.A.V. 10 W/V 360/15. Flying washed in 0745 hours - washed out 1000 hours. Washed in 1030 hours - washed out 1930 hours. Dual 1315 hours to 1930 hours. Dual 61 hr Total 111 hours. Total flying time 529.00 hours.
	15-4-43		0745 C.2 V.6 W/V320/5. Dual 0745 hours to 0830 hours. Washed in 0745 - washed out 1930 Night flying washed in 2030 - washed out 0530. Total flying time 738.30. Night flying 135.35 hours.
	16-4-43		0745 C.5 V.2 W/V170/10. Flying washed in 0745 hours - washed out 0845 hours. 1 hour limited dual. Snow and fog. Total flying time 38.30 hours.
	17-4-43		0745 C.A.V.10 Flying washed in 0800 hours - washed out 1930 hours. 112 hours sele. Night flying washed in 2030 hours. washed out 0530 hours. Total flying time 786.35.

REFERENCE TO APPENDICES

R.C.A.F. R. 65 20M-5-41 (188) H.Q. 1082-3-50