




5545 Gillmore's Improvements on Sash-holders.




5548 Wells' Revolving Drag-harrow.




5547 Widdifield's Improvements on Weather Strips.




5548 Newell & Cook's Improvement on Manner of Constructing Dead Pulleys.




5549 Cornell & Aldridge's Improvements on Barrels.




5550 Cornell & Aldridge's Improvements on Barrels and Cylindrical Box.




5551 Tandy's Improvements on Boilers for Steam Engines and Heating purposes.




5552 Howes' Improvement in Egg-beaters.




5553 Robinson's Improvements on Hand Corn-planters.




5554 Smith's Process for Heating Metals and Smelting Ores.




5556 Edy's Improvements on Fanning-mills.




5557 Johnson's Improvements in the "Eureka Pump."



5559 Beauchemin's Improvements in Kneading Troughs and Yeast Mills.



5560 Milner's Weather Strip.



5561 Grant's Improvements on the "Meadow Lark" Mowing and Reaping Machine.