

SHEAF-BINDING REAPING MACHINE.

FIG 1

DIAGRAM SHOWING POSITION OF ARMS BEFORE ENCLOSING CORN




FIG 2

DIAGRAM SHOWING POSITION OF ARMS AFTER BINDING SHEAF




FIG 3

ARM PREPARING TO BIND CORN






FIG 4

BUNDLE ENCLOSED PREPARING TO TWIST WIRE

FIG 7

POSITIONS OF BINDING WIRE





FIG 8

CUTTING THE WIRE AFTER COMPLETING THE TWIST

FIG 6

TWIST COMPLETED AND WIRE CUT. A SECOND TWIST ALSO HAVING BEEN MADE BELOW THE PINIONS AT THE SAMETIME. IN ORDER TO MAINTAIN A CONTINUOUS WIRE

