

	PAGE
<b>SPEED</b> ( <i>Continued</i> )	
effect of type of machinee.....	183
effect on fly-wheel weight.....	200
in machines.....	129, 188
table of.....	196
<b>SPIRAL</b> gear.....	75, 85
<b>SPRING</b> governor.....	170
design of spring.....	171
<b>SPUR</b> wheel.....	61
<b>STABILITY</b> in governors.....	160
<b>STAMP</b> mill cam.....	106, 107
<b>STANDARD</b> of comparison.....	28
<b>STEAM</b> engine, efficiency of.....	151
<b>STEPHENSON</b> link, valve velocity.....	57
<b>STONE</b> crusher, torque required.....	122
<b>STRESSES</b> in links due to acceleration.....	219
<b>T</b>	
<b>TANGENTIAL</b> acceleration.....	214
<b>TEETH</b> of gears.....	63, 64
cycloidal.....	64
height of.....	71
involute.....	69
mesh of.....	64
method of cutting.....	71
profile of.....	66
proportions of.....	72
slip of.....	68
<b>TOOTHED</b> gearing.....	61
<b>TORQUE</b> .....	126
<b>TORQUE</b> diagrams, cross compound engine.....	132
internal combustion engine.....	132
single cylinder engine.....	129
tandem engine.....	132
two cylinder engine.....	131
<b>TRAINS</b> of gearing.....	92
compound.....	92
<b>TRIPLEX</b> pulley block, Weston.....	101
<b>TURNING</b> moment diagram.....	125
<b>TURNING</b> pairs, friction in.....	146
<b>V</b>	
<b>VALVE</b> , velocity in Stephenson link.....	57
<b>VARIATIONS</b> of speed in machines.....	128
<b>VELOCITY</b> , angular.....	38
diagrams.....	36, 43
graphical representation.....	43
linear.....	31, 36
of piston.....	44, 45
of valve.....	41, 42
<b>VIRTUAL</b> centres.....	30
<b>W</b>	
<b>WEIGHTED</b> governor.....	160
<b>WESTON</b> triplex block.....	101
<b>WHITWORTH</b> quick-return motion.....	23, 57
<b>WORM</b> .....	86
<b>WORM</b> wheel.....	86
cutting of.....	90
<b>WORM</b> and wheel, ratio of speed.....	86
<b>WRIST</b> pin.....	9