AIRCRAFT SERVICES (WESTERN) LIMITED

0.

AIRCRAFT OVERHAUL - PROPELLOR OVERHAUL SALES & SERVICE - AIRCRAFT PARTS

> Telephone 61 231 P.O. Box 5, St. JAMES, Manitoba

> > June 12, 1950

5

Inspection Report Piper GF-EGB

Aircraft inspected. Tires and wheels removed inspected and found satisfactory. No major repairs or modifications found necessary.

D.A. Smith, Engineer.