

171. No person shall without authority remove any caution board, notice or danger signal, or pass any danger signal, caution board or fence.

172. Meetings of miners and other workmen in a body within the workings, or in any of the roads or air courses, or at the mine's mouth, are strictly prohibited.

173. No workman shall be permitted to enter, or to continue in the mine, while in a state of intoxication.

174. No person shall try the workings or the goaves for fire-damp with a naked light; and no person shall smoke tobacco, or take into any district of a mine which is worked with safety lamps tobacco pipes or tobacco for the purpose of smoking, or matches or any apparatus for striking a light other than that approved for lighting shots. All persons may be searched for tobacco, pipes and matches, but the person making such search shall first be examined by two of the workmen in the mine.

175. No person in a place of trust shall depute another person to do his work without the sanction of his superior officer, and no person in a place of trust shall absent himself without having previously obtained the permission of his superior officer for his term of absence.

176. It shall be the duty of any one receiving personal injury in or about the mine to immediately report such injury to the manager, overman or fireman.

177. No person shall be permitted to enter