

Equip. #	Equipment Description	Cost-Code	Manufacture	P.O.	Spare Parts
AREA 47 - GRINDING CIRCUIT					
47-41-007	Conveyor, Belt #7; Portable Stacker 30"	2040 3400	Texmarc Conveyor co.		
47-44-002	Crane, 40 Ton	2040 3010	Kaverit Steel	k1044	k1236
47-44-003	Crane, 5 Ton (Millwright Shop)	2040 3010	OMI Cranes		
47-55-012	Fan, Motor Cooling (SAG Mill)	2040 3025	Air System Supplies		
47-61-005	Compressor, Air, Fab Shop c/w Receiver	2040 3310	Gardner Denver	k1036	
47-63-001	Pump, Slurry #1 (SAG Mill Discharge)	2040 3500	Warman International	k1040	
47-63-002	Pump, Slurry #2 (SAG Mill Discharge)	2040 3500	Warman International	k1055	k1228
47-63-003	Pump, Slurry #1 (Primary Cyclone Feed)	2040 3500	Warman International	k1055	k1228
47-63-004	Pump, Slurry #2 (Primary Cyclone Feed)	2040 3500	Warman International	k1055	k1228
47-63-005	Pump, Slurry, Cyclone Feed - Standby	2040 3500	Warman International	k1055	k1228
47-64-002	Pump, Sump (SAG Mill Area)	2040 3500	Galigher 6"	k1059	k1223
47-64-003	Pump, Sump, Feed End (Ball Mill Area)	2040 3500	Galigher 6"	k1059	k1223
47-64-008	Pump, Sump, Discharge End (Ball Mill Area)	2040 3500	Galigher 6"	K1203	K1203
47-69-003	Receiver, Air, SAG Mill Clutch	2040 3310	Allis Minerals		
47-69-004	Receiver, Air, Ball Mill Clutch	2040 3310	Allis Minerals		
47-69-005	Receiver, Air, Ball Mill Clutch	2040 3310	Allis Minerals		
47-70-001	Breaker, Harmonic Filter SAG Mill	2040 3350			
47-70-002	Breaker, Bypass SAG Mill	2040 3350			
47-70-003	Breaker, LCI SAG Mill	2040 3350			
47-70-004	Breaker, Vacuum 4160V #1 Ball Mill	2040 3350			
47-70-005	Breaker, Vacuum 4160V #2 Ball Mill	2040 3350			
47-82-001	Pumpbox, SAG Mill Discharge #1	2040 3500			
47-82-002	Pumpbox, SAG Mill Discharge #2	2040 3500			
47-82-003	Pumpbox, Ball Mill Discharge #1	2040 3500			
47-82-004	Pumpbox, Ball Mill Discharge #2	2040 3500			
47-84-004	Chute, SAG Mill Feed	2040 3600	Transcontinental Eng.		
47-84-005	Hopper, Ball Feed to SAG Mill	2040 3600			
47-84-006	Chute, Ball Feed to SAG Mill	2040 3600			
47-84-007	Chute, Screen #1 O/Size Discharge	2040 3600			
47-84-008	Chute, Screen #2 O/Size Discharge	2040 3600			
47-84-010	Chute, Feed to Conveyor #4	2040 3600	Conveyor Eng.		
47-84-011	Chute, Feed to Conveyor #5	2040 3600			
47-84-012	Chute, Feed to Conveyor #7	2040 3600	Transcontinental Eng.		
47-84-013	Chute, Discharge From Conveyor #7	2040 3600	Transcontinental Eng.		
47-84-014	Hopper, Grinding Ball Feed	2040 3600			
47-84-015	Hopper, Grinding Ball Feed	2040 3600			
47-84-025	Chute, Flop Gate; SAG Mill Discharge	2040 3600			
47-84-027	Chute, Ball Mill #1 Discharge	2040 3600			
47-84-028	Chute, Ball Mill #2 Discharge	2040 3600			
47-84-056	Chute, Cone Crusher Discharge	2040 3600			
47-87-002	Splitter Box, Ball Mill Pumpbox Feed	2040 3600			
47-92-001	Liner Handler, SAG Mill	2040 3055	Mc Lellan Equipment	k1015	k1215
47-99-001	Nuclear Level Indicator	2040 3600	Ronan		
47-99-002	Nuclear Level Indicator (Top)	2040 3600	Ronan		
47-99-004	Nuclear Density Gauge (#1 Ball Mill Disch.)	2040 3350	Ronan		
47-99-005	Nuclear Density Gauge (#2 Ball Mill)	2040 3350	Ronan		