PLACE	DATE	TIME	SUMMARY OF EVENTS	REFERENCE TO APPENDICES
	1942			APPENDICES
Trenton, Ont.,	Oct. 2nd. (cont'd)		Course 63 Duration 27-9-42 to 20-11-42 Intake 50 Output Remaining 50 50	
			Accident: Harvard No. 3114, Wasp 8151, "C2" Crash. Occurred five miles North West of Sterling at 14:30 hours. W.O.2 Hurley, T.W. (R.71687) uninjured. P/O Harrison, R.N. (J.13087) uninjured. Occurred while practising aerobatics. Carburettor icing occurred when the engine stalled and fire occurred causing forced landing. (Carburettor ice) Throttle stuck in closed position.	il a
			Strength decrease: 4 Officers 1 Airman.	
	Oct. 3rd.		Temperature 39°, Dewpoint 37, Wind E.N.E. @ 8 m.p.h., Visibility 15 miles Ceiling unlimited.	
	,		Normal routine flying carried out.	0
			Strength decrease: 20 Officers 6 Airmen.	
Land to the state of the state	Oct. 4th.		Temperature 56°, Dewpoint 53, Wind S.E. @ 10 m.p.h., Visibility 10 miles Ceiling unlimited.	
			Flying washed out due to rain.	
			Total flying time for week ending 4-10-42. Total solo day 831:20 hrs. Total solo night 32:05 hrs. Total for week 863:25 hrs.	
			Total dual day 448:10 hrs. Total dual night 21:00 hrs. Total for week 469:10 hrs.	
PCAF D &			Total Link Trainer Time for week: - 159:45 hours.	1

R.C.A.F. R. 65 20M-5-41 (186) H.Q. 1062-3-50

PLACE

DATE

TIME

Page 2