

	PAGE.		
Separator speed indicators not satisfactory	196	Texture of cheese	
Separator vibration causes loss of fat	196	Thermometer, max. and min.	
Separator bowl clogging	197	Trunkle cheese	
Size of rooms	129	Value of milk or cream for buttermaking depends on fat	
Slime burned	197	Ventilation in ripening-room	
Snyder, Prof.	163	Walls of co-operative dairies	126,
Square cheese	180	Washing butter	
Steam boiler	139	Water for cooling ripening-room	
Stock book headings	115, 116	Weight of cheese marked on box	2
Storch, Prof.	185	Why:	
Stilton cheese	180, 181	Acidity at dipping	166, 167
Sub-earth duct	174	Acidity at milling	167
Swiss cheese	183	Acidity less than milk, at dipping	167
Systems of paying patrons 145-148		Too much acid cuts color	207, 208
Table of experiments in methods of paying patrons	147	Working better	
Temperature:		Young Canadian cheese	183
Effect on ripening cheese	176		
For separating milk	195		
For working butter	207		
For storing butter	219, 220		