

ALGARY  
Airport  
H 3765

1-58  
20

MODIFICATION REPORT CONTINENTAL  
ENGINE - #3887068, TYPE A65-8

Engine received at the Provincial Institute of Technology and Art for Piston Modification, the modification comprising the removal of cylinders, pistons, and connecting rods, and installation of new type pistons, rings and piston pins.

Continental Motor Corporation Modification Kit Part #EQ5390 comprising four new type pistons, one set new type rings, four new piston pin bushings and cylinder gaskets.

During this modification carbon was removed and valves re-ground. Engine assembled, installed back in aircraft CF-DGS and ground test run for five hours in accordance with Continental Overhaul instructions after fitting new pistons.

Installation of engine examined after ground test and found airworthy.

Total time since new	Hrs.		Mins.	
Time Since Complete Overhaul	Hrs.	—	Mins.	—
Time Since Top Overhaul	Hrs.	5	Mins.	15

*S. N. Green* Dec 6/46  
Signature "D" A790

*L. B. Swick*  
Signature

5082 (R)  
1162 (A)

DEC 7 1946