

16

5008-B18-14

1 Montgomery Avenue, Toronto 12,  
September 21, 1948

A25249

Mr. E.C. Thompson,  
Chief Engineer,  
Sky Harbour Air Services,  
Box 309,  
GODERICH, Ontario.

TRANSPORT-RECORDS  
SEP 22 A.M.  
File 5008-B18/14

Dear Sir:

It is noted that a letter originated from you requesting an extension of fifty hours on Continental 65 HP engine, Serial No. 3679758, installed in aircraft CF-BRN. In your letter you neglected to state the time this engine had already been operating. On receiving the log books in this office it was noted, on referring to the engine log book, that this particular engine had been operating 734 hours.

Therefore, this is to inform you that this aircraft is grounded pending engine overhaul, and our letter of September 14, 1948, granting fifty hours extension, is cancelled.

For your information, the time for major overhaul or remanufacture, for this type of engine, is shown in the Operator's Handbook as 600 hours.

The aircraft and engine log books are being returned under separate cover, via C.N. Express, so that the proper entries may be made regarding overhaul. The Certificate of Airworthiness is being held at this office.

Yours truly,

*D.W. Saunders*  
for (D.W. Saunders),  
District Inspector, Air Regulations,  
Toronto.

C.A. Brethour/MH  
cc: H.Q.

W