

**Partial table of pyrometric cones and their melting**

Cone	Fusing Points.	
	Degrees C.	Degrees F.
010	950	1742
06	1030	1886
03	1090	1994
1	1150	2102
3	1190	2174
5	1230	2246
9	1310	2390
13	1390	2534
14	1410	2570
15	1430	2606
20	1530	2786
25	1630	2966
26	1650	3002
27	1670	3038