All things in




## OUR STANDARD.

Result of a wreck in which a number of cars were demolished.

Illustrating Our Chine to Inde the to

THIS BEAM was under a Swift refrigerator car. The guide pins and fulcrum alone were destroyed. The Beam itself was straightened at our blacksmith forge without any special tools, and restored to service at a labor charge of fifteen cents. This clearly indicates that the Beam proper cannot be actually destroyed.



## OUR STANDARD.

Showing same Beam restored to its normal condition, ready for service.

Illustrating Our Claim for Indeathactellus.